

**Moab City Council Agenda Item**  
Meeting Date: September 24, 2019

**Title:** Crosswalks near the Moab Charter School

**Disposition:** Discussion and possible action

**Staff Presenter:** Chuck Williams, City Engineer

**Attachment(s):**

- Attachment 1 - Technical Memorandum: Crosswalks near the Moab Charter School

**Recommended Motion:** N/A

**Background/Summary:**

The City has received several comments from parents regarding students crossing 400 East and 300 South near the Moab Charter School. There are currently no designated school crosswalks serving Moab Charter School. Two pedestrian crosswalks were considered for conversion to school crosswalks to serve the Charter School: 400 East at Locust Lane, and 300 South at 400 East.

Utah Manual on Uniform Traffic Control Devices (MUTCD) governs use of crosswalks in Utah. Based on the process for warranting school crosswalk zones, found in the MUTCD, engineering staff have concluded that a school crosswalk and appurtenant signage (constituting a “school crossing zone”) are warranted for 300 South at 400 East, but not for the 400 east at Locust Lane location. See the attached Technical Memorandum: Crosswalks near the Moab Charter School. Additional coordination and communication are required with the Charter School’s administration regarding consistency with the school’s Safe Routes Utah map (formally SNAP), and additional measures will likely be necessary to promote student compliance with the proposed school crosswalk.